

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 15. W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 14 and 23

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Y. Birch (1/4s NBT) S 51° E 21 Links

9" Y. Birch (1/4s NBT) N 49° E 48 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two Hemlock B.T.'s. Both down and in poor condition. Iron marks visible on both. 10" Hemlock N 19° E, 28 Links
16" Hemlock S 41° W, 25 Links

Corner was placed and witnessed August 25, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/15/60
REGISTERED LAND SURVEYOR
Billy D. Buckler