

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46N N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 32-33.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 6/27/63

WITNESSES TO CORNER..... 12" Tamarack (1/4 S. N.B.T.) S. 40° W. 30 Lks.



12" Tamarack (1/4 S. N.B.T.) S. 50° E. 38½ Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between Section Corners.
No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7-29-63
REGISTERED LAND SURVEYOR
Billy D. Buckler