## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 46 \_ N.R. <u>16W</u>

	Schoolcraft	COUNTY
DESCRIPTION OF CORNER	Sec. Cor. common to Secs. 5, 6, 7 and 8.	
CORNER MONUMENT 1"	Pipe with 4" Aluminum Cap.	
DATE MONUMENT PLACED A	ND WITNESSED6_5_63.	
WITHESSES TO CORNER	9" W. Spruce (S. 7 N.B.T.) S. 24° W. 37½ Uks.	
	6" W. Spruce (S. 8 N.B.T.) S. 66° E., 20 Iks.	
<b>+</b>	18" W. Pine (S. 5 N.3.T.) North 70 Lks.	
	AND	
CIRCLE CORNER REGISTERS	ED	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one probable B.T., a Tamarack bearing N. 31 W., 40 Iks. Position checks with corners in all directions.

SURVEYOR'S SEAL

SIGNED Silly & Buckles DATE 1/26/63