

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 16-17 W


Alger and Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 18-19-13-24.

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 6/4/63

WITNESSES TO CORNER..... 14" Dead Cedar Stub (N.B.T.) S. 23° W. 20 Links.



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at an old Cedar post set by an unknown Surveyor.  
Position checks with Corners North and South and to Stream 50 Lks. East.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler DATE 7-26-63  
REGISTERED LAND SURVEYOR