

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 16-17 W


Alger-Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 7-12.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 6/4/63

WITNESSES TO CORNER..... 9" Cedar (1/4 S.N.B.T.) N. 24° W. 6 Links



CIRCLE CORNER REGISTERED

13" Y. Birch (1/4 S. N.B.T.) N. 70° E. 22 Links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportionate measure along township line. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 26, 1963  
REGISTERED LAND SURVEYOR