## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

			-	School <b>c</b> raft		COUNTY
DESCRIPTION OF CORNER	Section	Corner for	r sections	10-11-14-	-15	
CORNER MONUMENT	l" pipe	with 4" b	rass cap.	· - ·		
DATE MONUMENT PLACED AND	WITNESSED	9-12-	61			
WITHESSES TO CORNER	7"	tamarack	(SL4 NBT)	S40°E	27½ links	<del>.</del>
	911	tamara <b>c</b> k	(SlO NBT)	N57°W	78 links	· · · · · · · · · · · · · · · · · · ·
15		·	<del></del>	<del></del>		
	AND					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by double proportionate measure from corners 1 mile north; 1 mile east; 1 mile south and 1 mile west. No evidence of original corner.

SURVEYOR'S SEAL

Suchles DATE March 13, 1962 REGISTERED LAND SURVEYOR Billy D. Buckler