

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 22/23

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-18-61

WITNESSES TO CORNER..... 7" W. Birch (NBT 1/4S) N35°E 26 links



12" Cedar Stump (NBT 1/4S) S81°E 18 links

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was replaced from (cedar 15" N19°W 25 links) B.T. badly burned. Axe marks and inverted iron mark on overgrowth.

**SURVEYOR'S SEAL**

SIGNED Billy D. Buckler DATE December 29, 1961  
REGISTERED LAND SURVEYOR  
Billy D. Buckler