

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 46 N.R. 15-16 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER North 1/16 Corner between Secs. 19-24

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 2/27/64 with Wm. Miller, Aide

WITNESSES TO CORNER..... 13" Cedar (N 1/16 19/24 BE) S20°E, 15 Lks.



10" Cedar (N 1/16 19/24 BE) S59°W, 32 Lks.

AND

Corner lies 10 Links South of stream.

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was established midway between Section Corner to North and 1/4 Corner to South.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 9/21/64