

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 16 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 13-14-23-24

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 2/12/64 with Wm. Miller, Aide

WITNESSES TO CORNER..... 13" Cedar (S23 NBT) S26°W, 13 lks.



9" Cedar (S13 NBT), N48°E, 21 lks.

12" Soft Maple (S14 NBT), N39°W, 24½ lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at wood post with Tamarack B.T. bearing S5°E, 16 lks., tree down but scribe marks visible. Corner found by Wm. Miller, Aide.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9/21/1964
REGISTERED LAND SURVEYOR