MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T.47 NR_18_F.

			SeheelgraftCOUNTY
DESCRIPTION	OF	CORNER	1/4 Cor. between Sections 22 4-25
DESCRIPTION	OF	CORNER	MONUMENT_1" Pips_with 4" Brace cap
WIT TNESSES	то	CORNER	\$2"_ V Pine. Stub. < N. 14. V 98. Links
			16" T. Pine Stud = F 76 F 84 Janks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Ferestry Division survey erew, while making a partial resurvey of this Township. Two original B.T.'s still in place, one in good condition, one in poor condition.

Corner was placed and witnessed May 27, 1955.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 6/6/8 - -