

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.47 .. NR 13-14 W

..... Schoolcraft COUNTY

DESCRIPTION OF CORNER .. 1/4 Corner between Sections 25 and 30 ..

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 4" brass cap ..

WITNESSES TO CORNER 36" W. Pine Stp. .. S 42° E .. 60 links ..

34" W. Pine Stp. .. N 82° W .. 96 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two Section Corners.

No evidence of original corner.

Corner placed and witnessed August 29, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 9/4/56