

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 13 W..

----- Schoolcraft ----- COUNTY

DESCRIPTION OF CORNER .. 1/4 Section Corner between Sections 17 and 20 ..

DESCRIPTION OF CORNER MONUMENT ... 1" pipe with 4" brass cap .....

WITNESSES TO CORNER 24" W. Pine Stp. .... N 60° E .... 71 1/2 links .....

36" W. Pine Stp. .... S 56° E .... 81 links .....

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two Section Corners.

No evidence of original corner.

Corner placed and witnessed August 29, 1956.

SURVEYORS SEAL

SIGNED *Billy D. Buckler* DATE 9/4/56  
REGISTERED LAND SURVEYOR