

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 13 W.

----- Schoolcraft ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 21, 22

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 22" W. Pine Stump N 10°W 25 links  
Marked 1/4S NBT

36" W. Pine Stump S 5°W 31 links  
Marked 1/4S NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one W. Pine Stump bottom.  
Found traces of two stakes in soil at proper bearing and distance.

Distance checks with stream south and with Section Corner North.

Corner placed and witnessed October 30, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/8/56  
REGISTERED LAND SURVEYOR