

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 13-14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 4 Cor. bet. Secs. 13-18

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-6-70

WITNESSES TO CORNER..... 12" Jack Pine ($\frac{1}{4}$ S NBT) S9°E 37.6'



CIRCLE CORNER REGISTERED

10" Jack Pine ($\frac{1}{4}$ S NBT) S78°E 30.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Sec. Cors.
Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

10-19-70