

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N. R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 3-4

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-6-70

WITNESSES TO CORNER..... 13" B. Cherry (AS NBT) S56°W 33.5'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in shoulder and 10.5' south of road centerline.
This corner re-established on line and by single proportionate measure, between
two Sec. Cors.
Found no evidence of original Cor.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 10-19-70
REGISTERED LAND SURVEYOR