

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 16-17

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-17-70

WITNESSES TO CORNER..... 20" W. Spruce (N 1/16 BT) S13°E 5.4'



28" Hard Maple (BT) N67°W 12.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to north and $\frac{1}{4}$ Cor. to south.

Corner lies in hardwood type and in the SE corner of a recent timber cutting operation.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 10-15-70
REGISTERED LAND SURVEYOR