## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

TAY NR M. Y.

•			Schoolgraft COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Septions 32 A 32
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe sit 4" brase cap
WIT TNESSES	то	CORNER	
			26° V. Plag Syago - N. 36 B - 43 Make
			30° W. Pine Stupp - 0 6 2 - 21 Make

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey erow, while making a partial resurvey of this Township. One original B.T. still in place, in fair condition.

Gerner was placed and witnessed Fuly 29, 1953.

SURVEYORS SEAL

SIGNED C. June DATE 1/20/54 DATE 1/20/54