

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~47~~ NR. ~~24~~ W.

----- Schoolcraft ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 28, 29, 32, 33 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 16" Pine Stump - N 4 W - 21 Links -----

30" Pine Stump - S 26 E - 57 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by E. C. Hall, District Forester, of Shingleton. Two original B.T.'s in place, in good condition. A steel fence post has been placed erroneously 3 ft. NE of corner.

Corner was placed and witnessed July 17, 1951.

SURVEYORS SEAL

SIGNED Leah C. Sedgwick DATE 7/26/51  
REGISTERED LAND SURVEYOR