## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 47 NR 14 V

				Schoolcraft	COUNT'
DESCRIPTION	OF	CORNER	1/4 corner be	tween Sec. to 28-33	) <b></b>
DESCRIPTION	OF	CORNER	MONUMENT	l" pipe with 4" bra	se cap
WIT TNESSES	то	CORNER	15" W. Pine	s 79° w "1/4 s xbr"	62 links
			8" Red Pine	1/4 S KBT S 12° E "1/4 S KBT"	28 links
				*1/4 S MBT*	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from two white pine B.T.s bearing H 40° W 22 links and S 5° E 13 links. Stumps badly burned.

Position with corners east and west.

1/4 corner lies in old logging trail.

1/4 corner found by Forestry Division Survey Crew while making a retracement survey of this township.

Placed and witnessed 1/4 corner 7/10/57.

SURVEYORS SEAL

SIGNED Silly D. Suchles DATE 7/10/57