

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 14. W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 16 and 21

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 30" W. Pine Stub (1/4^s NBT) N 25° E 125 Links

50" W. Pine Stub (1/4^s NBT) S 12° E 21 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. Found no evidence of original corner. Found original line tree to east. Corner checks with this tree.

Corner was placed and witnessed June 7, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 8/11/60