Cons. 40 47 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

1.0M

		Schoolcraft	COUNTY
DESCRIPTION OF CORNER	1/4 Corner between Secti	ions 13 -14	
CORNER MONUMENT	1" Pipe with 4" Aluminum	n Cap.	
DATE HONUMENT PLACED AND WI	THESSED <u>8/16/67</u>		
WITHESSES TO CORNER	12" Hard Maple (1/45 NE	r) m8°5 9.61	
-	12" Hard Maple "	s63 ⁰ ,1 29.01	
- AN	ID		
CIRCLE CORNER REGISTERED —			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

T. 57

This corner replaced from one Hard Maple stump, bearing S60°E 25 links; a probable B.T. Found a down maple with chopped out face, bearing S30°W 30 links. This appears to be a witness but we find no record.

Found blazes to East & West of Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Euckler DATE 10/26/67

REGISTERED LAND SURVEYOR