

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 15W


Schoelercraft COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 19-20-29-30

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-29-69

WITNESSES TO CORNER..... 10" Soft Maple (S20 NBT) N23°E 27.7'



10" Soft Maple (S30 NBT) S30°W 24.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one original witness, a Soft Maple bearing N40°E 37 links.
Tree is still green with several old blazes.
Found several blazes facing corner location.

Corner lies on south side of an old logging road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3-24-70
REGISTERED LAND SURVEYOR