

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 15 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Section s 27-28-33-34

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/15/64 with Miller

WITNESSES TO CORNER..... 10" Cedar (S28 NBT), N 53° W, 50½ lks.



10" Cedar (S33 NBT), S 50° W, 32 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at Wood Post. Checks well with Line Tree to South and Corners in vicinity. Post set by Registered Land Surveyor Radcliff.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/14/1964
REGISTERED LAND SURVEYOR