

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 15 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Seds¹ 13-14-23-24

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/8/64 with Miller

WITNESSES TO CORNER..... 12" Y. Pine (S13 NBT), N 27°E, 116½ lks.



10" Y. Pine (S24 NBT), S 07°E, 100 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two (2) pine stumps in proper distance and bearing,
Small iron pin at corner with point of Wood Post.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler REGISTERED LAND SURVEYOR DATE 10/13/1964