

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 15W

Schoolcraft COUNTY


DESCRIPTION OF CORNER 1/2 corner between Sections 9-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-22-62

WITNESSES TO CORNER..... 18" W. Pine Stump (NBT) S18°W, 53 links

34" W. Pine Stump (NBT) N86°E 97 links



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners. No evidence or original corner.
Corner lies on west edge of old grade.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963
REGISTERED LAND SURVEYOR

Billy D. Buckler