

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T.47.. NR.15.W..

..... Schoolcraft ..... COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 1 and 2 .....

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap .....

WITNESSES TO CORNER 32" White Pine Stp. S 79° W 79 links .....

6" White Pine S 43° W 34 links .....

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner by Proportionate Measure between two Section Corners.

Hemlock stump bottom lies in proper position.

Corner placed and witnessed July 30, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/1/56  
REGISTERED LAND SURVEYOR