

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ corner between sections 4-9

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-21-62

WITNESSES TO CORNER..... 14" W. Pine ($\frac{1}{4}$ S NBT) S 22°W, 47 links



10" W. Pine ($\frac{1}{4}$ S NBT) N19°E, 111 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at wood post set by unknown surveyor. Position checks with other corners in area.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963
REGISTERED LAND SURVEYOR

Billy D. Buckler