

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 3-4-9-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-22-62

WITNESSES TO CORNER..... 36" Stump (S10 NBT) S53°E 43 links



26" Stub (NBT) N37°E, 90 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by Double Proportionate measure.
Corner lies in road intersection.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963
REGISTERED LAND SURVEYOR

Billy D. Buckler