

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N N.R. 15W

Schoolcraft COUNTY


DESCRIPTION OF CORNER  $\frac{1}{4}$  Corner between Sections 3-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-22-62

WITNESSES TO CORNER..... 16" W. Pine Stub ( $\frac{1}{4}$ S NBT) North 100 links

16" W. Pine stump (NBT) S50°W, 197 links



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one possible tamarack B.T. Corner lies in a low wet marsh.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE March 7, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler