

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T 46-47 NR 16 W ..

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 5 and 2.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 13" Soft Maple (1/4s NBT) S. 73° E 52 Links

13" Soft Maple (1/4s NBT) S. 15° W 43 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced as set by unknown surveyor. Found no positive evidence of bearing trees. One possible Hemlock.

Corner was placed and witnessed August 4, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 8/12/60