

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Secs. 22 and 27.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 5-15-63

WITNESSES TO CORNER..... 8" W. Pine ($\frac{1}{4}$ S. N.B.T.) S. 18⁰ E., 41 lks.



20" W. Pine ($\frac{1}{4}$ S. N.B.T.) N. 44⁰ W., 20 $\frac{1}{2}$ lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was replaced at wood Post with 4" tamarack down with scribe marks visible (S. 28⁰ E., 40 lks.) tam. 12" (N. 66 W., 28 lks.) in place but rotted badly.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/2/64
REGISTERED LAND SURVEYOR