

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 17/16

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-20-61

WITNESSES TO CORNER..... 16" Cedar (NBT 1/4S) S 17°E 38 links



18" W. Birch (NBT 1/4S) S 52°W 15 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners. No original evidence but several blazed trees near.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 29, 1961  
REGISTERED LAND SURVEYOR  
Billy D. Buckler