

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Schoolcraft COUNTY


T 47N R 16W

DESCRIPTION OF CORNER North 1/16 Corner bet. 11-12

CORNER MONUMENT 1 1/4" Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 3/18/68

WITNESSES TO CORNER..... 7" Soft Maple (N 1/16 BT) S87°W 11.4'



6" Soft Maple (BT) S72°E 11.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. 1/4 corner to south (in lake)
and Sec. Cor. to North.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

3-14-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
✓ Forestry Div., Lansing

R 4047
Rev. 10/68