

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 16 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER East 1/16 Corner Section 11.

CORNER MONUMENT 1" pipe With 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 11-6-69

WITNESSES TO CORNER..... 13" Hard Maple (E1/16 BT) S11°E 19.7'



9" Soft Maple (E1/16 BT) N51°E 2.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on the line between computed location of $\frac{1}{4}$ Corner, in lake, $\frac{1}{4}$ mile to the East and Center of the Section to the West.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 12-31-69
REGISTERED LAND SURVEYOR