

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Secs. 2-11

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 11-6-69

WITNESSES TO CORNER..... 10" cedar (1/2 S NBT) N60° E 25.0'



9" cedar (1/2 S NBT) S38° E 19.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed and re-witnessed at an old wood post set by Cleveland-Cliffs Iron Co. surveyors.
Found old blazes in vicinity of corner.
Position checks well to calls of record notes and to other corners in this section.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 1-26-70
REGISTERED LAND SURVEYOR