SURVEY & REMONUMENTATION

DEC 1 5 1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 DEC - 5 AM IO: 5R

reicistel of busis Affin Lives SHAWASSIT COUNTY, MICH.

or corners in REMONUMENTATION Located In: Corner Code ## 6hiawassee (County) T 5N R 2E **Public Land Survey** _. R . **Property Controlling** in Section Miscellaneous _ T .__ ___ R _

__ , Recorded Plat _ Private Claims _

__ R

Norman C. Caldwell , in a field survey on November to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land lanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

13 s 1/4 cor., Sec. 36, T5N-R2E

Property in Sec.

Wood post placed by J. Wampler, 1826 N86°W 16 lks. (10.56') 8" Sugar N72°E 19 lks. (12.54') 7" Sugar

No subsequent record

	A	В	С	D	E	F	G	н	l J	K	L	М
2		6		5		4	-;	3—	 _:	2	_	
3		<u> </u>	<u> </u>			<u> </u>	L	_				
4		ļ 7	$ldsymbol{f eta}$	 8	_,	ļ —	1		1	1	 1	2
5	L	_					L					
6		 18—	L,	 7	L,	 6	L.,	5	1	4	L.	3
7	L	Ĺ		Ĺ		Ĺ	L.	Ĺ				
8		 19—	L,	0	2	1		2	L,	3		4
9	L	Ĺ		Ľ		Ĺ	L	Ĺ.	_	<u>ٿ</u>		
10		30—	L.	9	L,	8			L_^	6		5
11		Ĺ		<u> </u>		<u> </u>		Ĺ			أ	
12		31	Ι.	2		3	Γ,	4	٦,	5—-		6—
13	Γ		Ι,			_				5—- 	_	

Register of Deeds Stamp & File Number

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

\$ 1/4 cor., Sec. 36, T5N-R2E

Set a temporary position using local collateral evidence. Dug a 15' x 15' x 3' deep hole. Fnd. a pointed stone and it agrees well with occupation 1/16 & Sec. cor., relationships. Set a standard 20" Harrison marker at this position as approved by Shiawassee County Peer Review Group and is accepted as a careful and faithful perpetuation of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: HOUSESHAMA

_-13 s 1/4 cor., Sec. 36, T5N-R2E

Fnd. pointed stone, replaced with a standard 20" Harrison marker at this position as approved by Shiawassee County Peer Review Group and is accepted as a careful and faithful perpetuation of the position of the original corner.

N80°W 152.90° Set p.k. & tag #12018 S. fc wood post S65°E 90.12' Set p.k. & tag #12018 N. fc wood fnc post S50°E 43.92' Set N & T #12018 NE fc 4" Elm

Set N & T #12018 NW fc 4" Elm

NOU

AT G 的复数

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983