MAY 28 1997

REMONUMENTATION

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

1 ^A

2

3

4 Ż

5

6

7

8

Q 10

11

12

В C

6

18

19

30

31

D

5

ß

-17

20

20

32

F G

Ó

16

21

28

33

H I

10

15

22

27

34

J K

2

11

14

23

26

35

12

13

24

25

36

96 AUG 16 PM 2: 37

REGISTER OF DEEDS

For corners in Corner Code # Shiawassee Located In: (County) SHIAWASSEE COUNTY, MICH. 1. Public Land Survey 5N R 3E K-9 R R R 2. Property Controlling R in Section s R Miscellaneous S R Register of Deeds Stamp & File Number Property in Sec. R S

, Recorded Plat 4. Lot No. 5. Private Claims

Norman C. Caldwell , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
- K-9 Sec. Cor. 23, 24, 25, 26, T5N-R3E

Wood Post placed by J. Mullett, 1825 S 30 W 28 lks (18.48') 18" W. Oak N 14 E 8 lks (5.28') 8" W. Oak

Survey by L. Mason, 1879. Recorded in Shiawassee County Surveyors records 1874-1883, P. 236, also 1879-1900, P. 34. Monuments and references not given.

Survey by E.F. Joslin, no date (1899 +/-). Recorded in, book E, P. 18. N 1/2 E 51 1/2 lks (33.99') 8" Y. Oak, N 54 E 78 lks (51.48') 6" W. Oak Monument not given.

Survey by O.M. Elliot, 1966 & 1971 recorded in Elliots field books, 44 at P. 49 and book 49 at p. 58. Found stake, road here filled 4', 2 times distance to 1/8 fence agrees with fence at SE Cor., Sec. 23. SW 28.4' E gate post SW 39.4' W gate post

Survey by E.J. McCombs, 1973. Recorded in Liber 1, P. 116 of corner. Found 3/4" pipe near of blacktop, N 1 E 54.45' 18" Oak, South 30.62' Found corner post, N 45 E 67.11' 18" Willow Found 3/4" pipe near centerline

Survey by M.L. VanRaemdonck, 1980. Recorded in L. 3, P. 411 of Surveys. Found 3/4" pipe, repeated ref.'s from L. 1, P 116.

Survey by M.L. VanRaemdonck, 1991. Recorded in L. 5, P. 937 of surveys. Found 1" pipe, N 45 E 46.80' SW fc 2" steel fence post, S 15 E 67.50' W. edge gas pipeline post, N 60 W 47.70' E. edge road sign post, S 40 W 105.70' Center of pump.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.
- Sec. Cor. 23, 24, 25, 26, T5N-R3E
 Found record 3/4" pipe per corner L. 1, P. 116 and surveys L. 3, P. 411 & L. 5, P. 937. Replaced with K-9 a standard 20" Harrison marker in a monument box as approved by Shiawassee County Remonumentation peer review group on 19 March 1996 and is accepted as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

K-9 OF MICH

g 50 W 39.63 #12018 tag in R.R. tie (R) #12018 tag in 8" Box Elder #12018 tag in 12" Aspen S 20 W 45.76 84.30 N 60 E #12018 tag in 10" Box Elder 54.681

Signed by Mile

Remonumentation

NORMAN C.

CALDWELL

PROFESSIONAL

SURVEYOR

1200

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

Surveyor's Michigan License No.

Peer Review Group