## SURVEY & **HEMONUMENTATION**

NOV 1 0 1997 COMMISSION RECORDED

97 NOV -6 PM 2: 37

REGISTER OF DEEDS


## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 SHIAWASSEE COUNTY. MICH.

For corners in		1	
Shiawassee (County)	Located in:	Corner Code #	
1. Public Land Survey	T_6N R_3E T R T R	_K-10	
Property Controlling     In Section	STR		
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp & File Number
4. Lot No. 5. Private Claims	, Recorded Plat		

Mark L. VanRaemdonck, in a filed survey on March 21, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this

- A. Description of original monument and accessories and/or subsequent restoration:
  - 1. Original: J. Mullett, DS 1823 Mon: Wood Post Access: B. Oak 36 West 17 Hickory 5 N73°E 6
  - 2. John Quine, Field Book #7, Page 74-75 8/5/1964 Mon: 3/4" Iron Pipe Access: Telephone Pole N32°W 32.3° Road name sign post N33'30'W 29.4' Stop sign post S74'W 46.3' Stake located at right angles 23.5' NW from centerline of pavement
  - 3. John Quine, Cert. Survey, Rec. L. 1, P. 531 9/6/1973 Mon: 3/8" X 6" iron Bolt Mon: 3/8" X 9" Iron Boit
    Access: Telephone Pole N32"W 32.3'
    Road name sign post N33"30"W 29.4'
    Stop sign post S74"W 46.3'
    Stake located at right angles 23.5'
    Northwest from centerline of pavement
  - 4. Karol R. Piotrowski, L. C. R. C., Rec. Liber 1, Page 185, 2/28/1974 Mon: 3/4" Iron pipe Access: Telephone Pole N32"W 32.3" Road Sign Post N33°30°W 29.4° Road Sign s74°W 47.8° Telephone Pole S60°E 78.67°



## APPROVED

County Remonumentation Peer Review Group NU 31 OUT 97



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" Pipe as referenced in No. 2, 4, 5, 6, 7, 8, 9 and 10. I accepted this position as the original corner location based on the best available evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner

Removed 3/4" Pipe. N05"W N25"W Installed a standard Shiawassee County Harrison Marker, stamped "Remon 24622." The marker is witnessed by the following accessories:

32.29' 59.67' 78.72' Set N&T #24622 in E. face 12" Scotch Pine Set N&T E. face Util, Pole Found N&T #12034 in S. face Util, Pole

\$60°E 104.70 Set N&T #24622 in SE face 8" White Ceda Centerline Lansing Road

Signed by

=Surveyor's Michigan License No.\_\_

Date OCT. 28, 1997

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 16, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983