SEP 2 9 1994

RECORDED

2 \* \*\*\* \*\*\*

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE 94 SEP -6 ANTH: 06 Filing Requirement of Act 74 Mich PA 1970

For corners in  Shiawassee (County)		r mig riequ	irement of next 14, minute 1.	REGISTER OF DEEDS			
		Located In:	Corner Code ≠≠	Laye Sunda			
1.	Public Land Survey	T 6N R 3E	L-11	SAYU Shulton SHIAWASSEE COUNTY. MICH.			
		T R T R T R					
2.	Property Controlling in Section	S T R S T R					
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number			
4.	Lot No,	Recorded Plat		A B C D E F G H I J K L			

Norman C. Caldwell	, in a field survey or	l	July 19	94 .
do hereby certify that under rec	quirements of P.A. 74, N	Michigan P.A. of 1970, the c	orner point	smentioned
in lines 1 and 2 above were in				
current manual of survey instri	actions of the United S	States Department of the I	nterior, Bur	eau of Land
Management or by a decree of				
above were in conformance wit				
Count of Low potablished .	a actablished manu	montad to manumented	recovered	found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	В	C _	D	Ε	F_	G	Н	ı J	K	L	М
2		6		5 —		[	L.	3	;	2	1	
3	_	<u> </u>				L	_					
4		ļ	L	 8—	_,	9	L,	0-	1	1	_,	2
5		L	L	<u> </u>		<u> </u>	L			L		L
6	  1	  8	<b>↓</b> .₁	   7	11	 	Ļ,	  5	1	4	_	3
7	L	乚		L	L	L.	<u> </u>			L		
ŝ	<u>_</u> ,	9	<u> </u> _2	20—	_2	 !1	<u> </u> -2	  2	2	3	2	
9	L_	<u> </u>		<u> </u>	乚	_	<u> </u>	<u> </u>	ļ	ļ		
10	<b> </b> _3	0	_2	 29—	_2	8	<u> </u> _2	27——	2	 		 !5
11			<u>L.</u>	<u>L</u>	<u> </u>	L	L	L	L_			
12			L,	[			Ĺ,			5—		6
	Ι `	í	1	ī	ľ	ĩ	`	ī	`	ĭ	`	ĩ

Description of original monument and accessories and/or subsequent restoration:

1/4 cor., Sec. 25 & 36, T6N-R3E

5. Private Claims \_

expressed below:

Wood post placed by J. Mullett, 1823 NO8°E 129 lks. (85.14') 13" B. Oak S14°W 109 lks. (71.94') 6" Tamarack

Survey by A. Huggins, Co. Surveyor, May 1849, recorded County Surveyors record Book A pg. 83 & CO. Surveyors record Bk B pg. 19, S.C.R. Mon. & Refs. Not Given

Survey by E. Mason, Co. Survey, June 1983; recorded in County Surveyors records 1879-1900, pgs. 104-105, S.C.R. S42°E 35 1/2 lks. (23.43′) 10" Tamarack

Unrecorded survey by J. F. Quine, Aug. 1964, recorded in Field Book #7, Pgs. 74-75 Cor. position occupied by 8" diam. wooden cor. post 4' high. Fnc. runs E-W and N.

Unrecorded surveys by E.E. Anderson, Dec. 1976, Set. iron at fnc. cor. w/wire to North N30°E 9.25' to 6" Locust

11.75' to fnc. post 9.75' to 12" locust (dead 6/94) S15°W

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-11 1/4 cor., Sec. 25 & 36, T6N-R3E

> Fnd. 3/8" rod w/cap #11495 against S. side 8" diam. wood post 4' high fnc. running E-W & N per Quines and Andersons records. Replaced 3/8" rod w/a std. 20" Harrison marker as approved by the Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

## APPROVED

County Remonumentation Peer Review Group 8/16/94 M.LV.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/4 cor., Sec. 25 & 36, 16N-R3E

Fnd. 3/8" rod w/cap #11495 against S. side 8" diam. wood post 4' high fnc. running E-W & N per Quines and Andersons records. Replaced 3/8" rod w/a std. 20" Harrison marker as approved by the Shiawassee County Peer Review Group and is accepted as the best available evidence of the

position of the original corner.

West 11.69' Fnd. Nail S. fc. fnc. post (R)

N55°E 9.36' Set N & T #12018 SE fc. 14" Locust (R)

N63°W 21.41' Set N & T #12018 S. fc. 12" Locust

506°W 27.81' Set N & T #12018 W. fc. 8" Locust

Surveyor's Michigan License No. \_

SINE OF MICH **MORMAN C** CALDVEELL Surveyor No. A Section of the sect

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983



Date