SURVEY & REMONUMENTATION

SEP 2 9 1994

RECORDED

LAND CORNER RECORDATION CERTIFICATE

94 SEP -6 AIIII: 06

COMMISSION For corners in

Private Claims .

Filing Requirement of Act 74, Mich. P.A. 1970


1-1-1

REGISTER OF DEEDS

| Shiawassee (County) | | Located In: | Corner Code ## | SHIAMASSEE COUNTY, MICH. |
|------------------------|-----------------------------------|--------------------------------|----------------|---------------------------------------|
| 1. | Public Land Survey | T <u>6N</u> R <u>3E</u> T R | м-11 | SHIAWASSEE COUNTY, MICH. |
| | | T R T R | | |
| 2. | Property Controlling in Section | S T R S T R | | |
| 3 . | Miscellaneous Property in Sec. | S T R S T R | | Register of Deeds Stamp & File Number |
| 4. | Lot No | , Recorded Plat | | ARCDEEGHIJKI |

July , 19 94 , Norman C. Caldwell _ , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Sec. cor., Common to Sec. 25 & 36, T6N-R3E & Sec. 30 & 31, T6N-R4E

Wood post placed by J. Mullett, 1823 NO5°W 187 lks. (123.42') 14" W. Oak S11°W 103 lks. (67.98') 9" W. Oak

Survey by E. Mason, Co. Surveyor June 1883, recorded in county surveyors records 1879-1900 pgs. 104-105 S.C.R. Non. - Not Given 840 1/2°E 56 lks. (36.96') 14" W. Oak N33 1/2°W 40 lks. (26.40') 18" B. Oak

Survey by K. R. Piotrowski, March 1974, recorded Survey by K. R. Piotrowski, March 1974, records in L. 1, pg. 207 of corners Fnd. T-bar, agrees w/original ties, at edge of gravel road. S55°W 32.52′ 18" Clump of Oaks N30°W 25.07′ 33" Oak N40°E 77.00′ 12" Wild Cherry

Description of corner evidence found and/or method applied in restoring or reestablishing corner: R

Sec. cor., Common to Sec. 25 & 36, T6N-R3E, & Sec. 30 & 31, T6N-R4E

Fnd. I-bar at edge of gravel road (Geeck Road) per L. 1, pg. 207 of corners, replaced w/std. 20" Harrison marker as approved by the Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

Measurements along the range line agree with E. Mason Survey of 1883.

APPROVED

County Remonumentation Peer Review Group 8/16/94 M.L.V.

Fnd. T-bar at edge of gravel road (Geeck Road) per L. 1, pg. 207 of corners, replaced w/std. 20" Harrison marker as approved by the Shiawassee County Peer Review Group and is accepted as the best sniawassee county Peer Review Group and is accepted as the available evidence of the position of the original corner. N30°W 22:06′ Set N & T #12018 N. fc. 33" Cherry S60°W 37.60′ Set N & T #12018 N. fc. 14" Oak S40°E 49.12′ Set N & T #12018 N. fc. Tri Oak (10" Ave) West 26.09′ Set N & T #12018 N. fc. 8" Oak

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11 Sec. cor., Common to Sec. 25 & 36, T6N-R3E, & Sec. 30 & 31, T6N-R4E

Find. T-bar at edge of gravel road (Geeck Road) per L. 1, pg. 207 of corners, replaced w/std. 20" Harrison marker as approved by the NORMAN C CALDWEL PROPESSIONAL SURVEYOR No. ession and service and service

1201

AU6

Surveyor's Michigan License No. ___

_ Date _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1978

REVISED MAY 14, 1975 REVISED JAN., 1983