NOV 1 0 1997

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 OCT 15 PM 12: 15

For corners in							REGIS	STER O	FDEE	DS
Shiawassee (County)	Located In:		Corner Code #				N.	100	le de	
(County)	Middlebur	y Township	•			SH	IAWAS	yer gr	OUNTY	. MICH
1. Public Land Survey	T 7N R T R T R		<u>K-9</u>			ı				
2. Property Controlling in Section	STR									
3. Miscellaneous	SK_			Regi	ister of	Deeds :	Stamp	& File	Numb	er
Property in Sec.	S T R		·							
Mendy A. Papin to hereby certify that under r n lines 1 and 2 above were surrent manual of survey instruction Management or by a decree of bove were in conformance w	equirements of P.A. 74, M in conformance with regretations of the United State a Court of Law and/or trith the rules of the Michic	n a field survey fichigan P.A. of gulations and r gulations and rea tast Department tast Board of L	on June 1970, the corner points mention ules therefore as required in nt of the Interior, Bureau of La oints mentioned in lines 3, 4 an	19 97, ned the and do 5	1 A B 2 6 3 4 7 5 18 7	5 8 17	4 9 16	3 10	2 II	1 12 13
Court of Law; established, re-established, monumented, re-monumented, recovered, expressed below:				as	8 19	20	21	22	23	24
IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					10 <b>3</b> 0	29	28	27	26	25
. Description of original monument and accessories and/or subsequent restoration:					12 31	32	33	34	35	36
	23, 24, 25, 6 26,									
N 47 W 38 1ks	d by R. Thomas, D.; (25.08') 30" Elm (13.86') 18" Elm	S., Jan. 18	31							

Survey by J.B.Parks, County Surveyor 1853, Recorded in Book B, P.38, S.C.R. Monuments and references not given

Survey by I.E. Brands, Surveyor, 1912, Recorded in sm red misc. drain book Monuments and references not given

В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-9 Section Corner 23, 24, 25, & 26, T7N-R1E

> Found 3/4" pinched pipe in centerline Krouse Road, origin unknown. Good fence line South. The distance along the Section line between Section 24 and 25 fits well with the I.E. Brands record (C.S.= 80.32ch = 5301.12' Meas. = 5309.67'). The distance along the Section line between Section 25 & 26 does not fit well with J.B. Parks record (C.S. = 79.87ch = 5271.42' Meas. = 5301.14'), it appears to be off a 0.5 chain. Occupation at the N. E-W 1/16 line measures well with the split (split= 1316.99' Meas. = 1316')

This position is accepted as the best available evidence of the position of the original corner.

Approved by the Shiawassee County Peer Review Group, Sept. 4, 1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 Section Corner 23, 24, 25, & 26, T7N-R1E

> Replaced 3/4" pinched pipe with a standard 20" Harrison monument in centerline gravel road, 0.40 below surface.

Set PK nail and tag #39096 in W. face 16" round wood post

31.33' Set hail and tag #39096 in NW face 16" twin Poplar Set PK nail and tag #39096 in NE face 14" wood post Set PK nail in East face P/P N50W 51.10

**APPROVED** 

County Remonumentation 10 er Review Group

ELMNIAL I

MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

MICH'O

g F

WENDY A. PAPINEAU PROFESSIONAL SURVEYOR

> No. 41919