NOA TO 1881

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 OCT 15 PM 12: 15

REGISTER OF DEEDS

For co	orners in	t	, •					/	P	
Shiawassee		Located in:	Corner Code #		Ange Sheelder SHIAWASSEE COUNTY, MICH			n/		
	(County)	Middlebury Townsh	ip .		×	, 31	JIAWA!	รริยย์ ด	COUNT	Y, MICH.
1. Pu	blic Land Survey	T 7N R 1E T R T R	<u>M-9</u>							
in 3. Mi	operty Controlling S_ Section S_ scellaneous S_	TR TR TR		Regis	ster of D	eeds S	Stamp	& File	Numb	er
	operty in Sec. S t No	TR			4 6	^ ~				
5. Pri	vate Claims				AB	C D	Ł + <	<u> </u>	l J K	LM
					2 6	5	4	- 3	2	1
t _.	Wendy A. Papineau	in a field surve	ey on June 1997	·	4 7	8	9	10	เบ	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				•	5 6 18 7	17	- 16	15	14	13
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			1	8 19	20	21	22	23	24	
NOTE	: Not more than 4 corn	ers, all in the same town a	, all in the same town and range, may be recorded	1	30	29	28	27	26	25
	on this certificate.				2 31	32	33	34	35	36
A. I	Description of original m	onument and accessories a	nd/or subsequent restoration:	1	13	<u> </u>	<u> </u>		L	
<u>M-9</u>	Standard Corner Sec Wood post placed by N 34 E 8 lks (5.28	etion 24 & 25, T7N-R1E 7 R. Thomas, D.S., Jan. 3') 10" Elm	1031		÷					
	S 41 W 4 1ks (2.64			AF	opp	n	VE	n		
		2022 2	0 7 60 6 6 7	~ ~ ~	- N	No. of the Co.	W L_	₩#		

L.C.R.C. by J.S. Fokens, 1977, recorded L. 2 P. 62 S.C.R.

Fnd N & T

N 45 W 43.29' N & T corner post

N 40 W 32.35' NW corner headwall S 40 W 27. 85' SW corner headwall

L.C.R.C. by N.C. Caldwell, 1992, recorded L.2 P.815 S.C.R.
Fnd rec. nail per L.2 P. 62, replaced w/ 1/2" bar & #12018 cap in monument box
N 45 W 41.46' Fnc Corner post (R)
N 40 W 40.10' "T" top C.M.P.
S 40 W 37.21' "T" top C.M.P.

East 18.82' sign post North 66.00' 1/2" bar with cap #12018

Survey by N.C. Caldwell, 1992 & 1996 recorded L.6 P. 124 and L.7 P.790 See L.C.R.C. L.2 P.62 for monument & references

Surveys by M.L. Vanraemdonck, 1995 & 1996, recorded in L. 7 P. 259 and P. 669 See L.C.R.C. L.2 P.62 for monument and references

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Standard Corner Section 24 6 25, T7N-R1E Fnd 1/2" rod with cap #12018 in Monument box per records above. This position fits well with <u>M-9</u> I.E.Brands record (C.S.= 80.32 ch= 5301.12' Meas.= 5309.67').

This position is accepted as the best available evidence of the position of the original corner.

Approved by the Shiawassee County Peer Review Group, Sept. 4, 1997

- Description of manument for corner and accessories established to perpetuate locating the position of the corner: C.
- Standard Corner Section 24 & 25, T7N-R1E <u>M-9</u>

rod with cap #12018 with a standard 20" Harrison marker in existing monument box Replaced 1/2"

Fence corner post Chiseled "T" in top of 48" C.M.P. Chiseled "T" in top of 48" C.M.P. N40W 40.10' 37.201

18.821

Sign Post 1/2" rod with cap #12018 in mon box (A-9 T7N-R2E) North 66.00'

OF MICHIG WENDY A. PAPINEAU **PROFESSIONAL** SURVEYOR No. 41919

Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAM., 1983 RD PROCESSING MARCH, 1983

County Remonumentation

Peer Review Group

NIC NIC 97