SURVEY & REMONUMENTATION

:0120-	Filing Requi	ER RECORDATION CERTI Frement of Act 74, Mich. P.	.A. 1970
Shiawassee	AMISSIONLocated in:	Corner Code #	94 NOV 16 PM 3: 41 REGISTER OF DEEDS
(County)	T <u>7N</u> R <u>2E</u> T <u>R</u> TR TR	(L-11)	SHIAWASSEE COUNTY, MICH.
2. Property Controlling in Section	STR STR		
3. Miscellaneous	STR		Register of Deeds Stamp & File Numl
Property in Sec.	srR		riegister or beeds ording a tine warm
	, Recorded Plat		A B C D E F G H I J K 2 6 5 4 3 2
			3 4 7 8 9 10 11 1
I, Mark L. VanRaemdonck, in a field survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2			
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			0 10 10 24 22 23 2
Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land			9
Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:			10 - 30 - 29 - 28 - 27 - 26 - 2
			11
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12 31 32 33 34 35 3
A. Description of original r	monument and accessories and/o	r subsequent restoration:	
1.) Original: William Broo Monument: Wood Accessories: W	kfield. 1824. d post /. Oak 24 N45°E 23 W. Oak 8 S59½°E 83		
2.) E. F. Joslin, County Su Monument: 5/8" i			•

3.) E. S. Brewer: L.C.R.C. recorded Liber 2, page 194. 8/1/79.

Accessories:

Monument: R.R. spike
Accessories: Cen. tele. pole & box \$331/2°E 29.6°

W. Oak 7" N2°W 35 links

Butternut 4" S25½°W 52 links Cherry 7" S39°W 55 links

Cen. 10" Oak anchor post S70 3/4°E 86.0' Cen. 14" Cedar in yard S24°W 88.8' Cen. 18" Apple tree N63°E 77.5'

4.) John D. Matonich: L.C.R.C. Liber 2, page 548. 4/22/88.

Monument: Found iron

SW 88.4' 12" Cedar North 16.33' R.E.I. Iron Accessories:

S60°W 35.40' Mail box #451 S45°E 29.37' N&F SE face P.P. N50°E 77.32' N&F SE face 16" Apple

(continued on reverse side of this sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. E. F. Joslin's monument and accessories have been obliterated. Found R.R. spike as referenced in no. 3, 4 and 5 above. Found no conflicting evidence and accepted this location as the best available evidence of the original corner MICHIGANIA location. Excavation for installation of Harrison marker provided no further evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:

\$50°W 102.02' Set N&T in NW face 12" Pine \$20°W 88.63' Set N&T in E. face 18" Cedar S40°E 29.44' Set N&T in NE face utl. pole

S70°E 88.89' R&C #24622 @ 33' R/W line N70°E 77.63' Set N&T in NW face 18" Apple

Surveyor's Michigan License No. 24622

APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971) REVISED MAY 14, 1973 REVISED JAN., 1983

APPROVED

County Remonumentation

Peer Review Group

9/27/94 M.L.V.

LIBER IR PG

OF MICHIGAN SU. 2462.

I A N D

VD SURVE VANRAEMDONCK

A. Description of original monument and accessories and/or subsequent restoration:

(continued from front)

5.) M. L. VanRaemdonck: Survey recorded Liber 6, page 806. 6/10/92.

.. VanRaemdonck: Survey recorded Liber 6, page 806. 6/1
Monument: R.R. spike
Accessories: SW 88.40' 12" Cedar
North 16.33' R.E.I. iron
S60°W 35.40' Mail box #451
S45°E 29.37' N&F SE face P.P.
N50°E 77.32' N&F SE face 16" Apple
S45°E 29.15' NW face U/P
S15°W 88.65' Cen. 15" Red Cedar
North 1.5' Phys. centerline
N60°E 77.80' Cen. 20" Apple