MAY - 1 1995

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corners in	
Shiawassee	

COMMISSION

94 NOV 16 PM 3: 44 Corner Code #

REGISTER OF DEEDS

SHIAWASSEE COUNTY, MICH.

Register of Deeds Stamp & File Number

GHI

26

(County) T 7N R 3E (L-11)1. Public Land Survey R R 2. Property Controlling R R in Section R Miscellaneous R Property in Sec.

Located in:

2

3

5

6

7 8

Q

10

11

12

13

, Recorded Plat 4. Lot No.

5. Private Claims

I, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Joseph Wampler, D.S. 1822

Monument: Wood post Accessories: W. Oak 10" N68°E 15 Elm 7" S66½°W 5

- 2.) Survey by Monroe Holley, 1853, of Section 25, T7N-R3E, Gives no monument or accessories.
- 3.) Survey by Monroe Holley, 1854, of Section 36, T7N-R3E. Gives no monument or accessories.
- 4.) Survey by Ezra Mason, Section 25, T7N-R3E. Gives no monument or accessories.
- 5.) Survey by Ezra L. Mason, Section 36, T7N-R3E. Gives no monument or accessories.
- 6.) Survey by E. F. Joslin, CR Book 17, page 130, Section 25, T7N-R3E. Gives no monument or accessories.
- 7.) M. VanRaemdonck: Survey recorded Liber 6, page 247.

Monument: Rerod and cap #24622 Accessories: North 8.07' Set N&T E. face S. trunk 24" twin Oak S65°E 7.53' Set N&T in S. face 4" W. Oak East 20.16' Set N&T in S. face 10" Ash S40°E 32.65' Set N&T in W. face 10" Cottonwood

8.) E. S. Brewer: Survey recorded Liber 6, page 588. Monument and accessories same as no. 7 above. APPROVED

County Remonumentation Peer Review Group 10/18/94 M.L.V.

OF MICHIGA

MARK L.

VANRAEMDONCK LAND

SURVEYOR

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Calculated the distance between South 1/2 corner Section 36 to occupied center of Section 25. Equals 8153.21 feet. Distance shown in survey by Mason in Section 36 (5574.36) and Holley in Section 25 (2585.58) equals 8156.94. Located point on North and South 1/2 line fence at Holley's distance from center on Section 25 at this location, I found a 5" x 8" x 5" stone. This stone is 2627.12 feet East of the Northwest corner of Section 36. Holley's survey gives this distance as 2628.78 feet. I accepted the location of this stone as the careful and faithful perpetuation of the original corner location.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:

N60°W 4.69' Set N&T S. face 24" Oak N20°W 7.55' Set N&T e. face 18" Oak N70°E 8.15' Set N&T S. face 12" Elm 13.51' Set N&T NE face 14" Elm S60°W 13.42' Set N&T E. face 8" Elm

MI RED LAND Date Nov. 9, 1994

Surveyor's Michigan License No. 24622

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18. 1971 REVISED MAY 14. 1975 REVISED JAN., 1983

1R