

A. Continued:

1972 Act 74 L. 1, P. 75 & CPCo survey by E. M. McCombs, DWG No. S-F17562, Sheet 21, Rev. C, found 1" pipe in centerline gravel
8" Maple W 39.73'
T iron W 33.0'
14" Willow S10E 62.63'
10 " Wild Cherry N10W 78.66'

Undated Act 132 by B. Griggs; fnd nail.
West 33.0' T-Iron
East 36.15' Nail in 5" Cherry
N60W 162.15' SE corner H# 1630
N60E 95.50' SW corner H#1637

1972 Act 132 by K. Piotrowski, found 1/2" re-rod
8" Wild Cherry East 36.21'
10" Maple West 40.0'
13" Ash S15E 62.61'

1975 Act 74 by J.F. Quine L. 1, P. 493; fnd 3/4" iron pipe stake drove to 3" deep in gravel road, used witnesses from 1964.

1989 Act 74 by N.C. Caldwell L. 2, P. 656; fnd 1" pipe in CL gravel
West 39.75' 8" Maple
West 33.0' "T" Iron
S10E 62.63' 14" Willow
N10W 78.66' 10" Cherry

SURVEY &
REMONUMENTATION

NOV 03 1998

SECTION



3007720
Page: 2 of 2
10/27/1998 03:22P

Kaye Grubba - Shiawassee Co. REMON

Lb-1 Pg-273