JAN 1 6 2001

LAND CORNER RECORDATION CERTIFICATE

2000 Remonumentation Program

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•									
SHIAWASSEE (County)	Located In: Venice Twp.	Corner Code						3044 Page 12/04	410	1 09:53A
1. Public Land Survey	T <u>7N</u> R <u>4E</u> T R T R	<u>C-1</u>	Kaye Grubbs	- Shiawass Registe	ee Co.	REMOI	mp & F	ite Nun	Y-330 aber	- 3
Property Controlling S	T R T R T R T R T R T R T R T R T R T R		APPR VCL 27/ ounty Rem Peer Rev	OVE	Dation		<u> </u>			
4. Lot No, Recorded Plat 5. Private Claims			1 cei nev	2 3	6	5	4	- 3	2	- 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
I,John H. Rauser, P.S. do hereby certify that under requirem	in a field survey on _ ents of P.A. 74, Michi	August igan P.A. of 1970, t	20 he corner points	00 mentioned 5	<u> </u>	8	9	10	11	12
in lines 1 and 2 above were in conficurrent manual of survey instructions Management or by a decree of a Courlabove were in conformance with the r	ormance with regulat of the United States of Law and/or that t	tions and rules the Department of the the corner points m	erefore as requi e Interior, Burea entioned in lines	ired in the 6 au of Land 7	18	17 20	16 21	15	14	13
Court of Law; established, re-est expressed below:	ablished, monument	led, re-monument	ed, recovered,	found as 9	30	29	28	27	23	24 25
NOTE: Not more than 4 corners on this certificate.	, all in the same to	own and range,	may be recor	ded 11 12 13	31	32		34		36
18 IK\$ (11.88') Co	o Section 5 & 6, T7 Wampler, D.S., Section C-13 to T8N-F	N-R4E, Venice T t wood post, witr R4E, C-1to C-2 =	ownship, Shian	ent restora wassee Cou E 6 lks (3.96	<u>nty</u> i') 4" Asl			٠, ١	.132	H, Eas
1851 County Survey, F	⁹ . 125 Book "A", Pg 1 to B-1= 40 ch (26	i. 87, Book "B", P	g. 23 by Monn	oe Holly,D.S	. Monur	nent de	scriptio	n-none	given,	
B. Description of corner evi C-1 Closing Corner common to	dence found and Section 5 & 6, T7	d/or method ap N-R4E, Venice T	oplied in rest ownship, Shiav	toring or re	establ nty	ishing	corne	r:		
Found no evidence of the T8N-R4E. Calculated en noted in GLO notes on I 0.05 feet East and 0.28 the found wood post be and that it be replaced were replaced were recommended.	xcavation positior ine with C-13 and feet North of the o accepted as a ca	n based found v I B-13. Excavat calculated posit reful and faithfu	vood post at (ted and found ion. Measure il perpetuation	C-13 and jo I wood post ed East to C n of the pos	g distar : 3'+_bel :-13, 11	nce of flow roa .93 fee	18 links Id grav	i (11.88 el in ori recomi	3'), as ginal s mend f	soil, that
		1	.,							
C. Description of monument corner: C-1 Closing Corner common to		•				ing the	e posit	ion of	the	
N70W 81.30' Set N&T N70E 67.81' Set chise	#39096 in old blaze #39096 in SE root eled "x" on top of Noteled "x" on top of So	e of a 30" Hickon of 54" Oak orth end of 21" cu	y tree (west fac ilvert	e) STATE	OF MIC OHN H AUSE	(CA)			Man Anna Caran	

Signed by / / / / Surveyor's Michigan License No. 39096

PROFESSIONAL