## SURVEY & REMONUMENTATION

## 1998 REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

NOV 03 1998

SECTION For corners in Located In: Corner Code # Shiawassee Page: 1 of 2 **New Haven Twp** (County) 10/27/1998 03:229 Lb-1 Pg-269 1. Public Land Survey Register of Deeds Stamp & File Number 2. Property Controlling S in Section Miscellaneous Property in Sec. CDEFG H I J K\_, Recorded Plat 4. Lot No. 2 3 2 1 5. Private Claims 3 4 Q าก 8 41 -12 , in a field survey on John H. Rauser, P.S. February 20, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 6 current manual of survey instructions of the United States Department of the Interior, Bureau of Land 7 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 18 17 16 15 14 13 19 20 21 22 23 24 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 9 expressed below: 10 30 29 27 25 28 26 11 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 12 33 34 35 36 on this certificate. 31 -32 13 Description of original monument and accessories and/or subsequent restoration: Section Corner, Sections 23,24,25 & 26, T8N-R3E, New Haven Township No accessories given 1822 G.L.O. Joseph Wampler, D.S., 10" Elm at corner Surveys by H. C. Main, C.S.; Stake & Stone, measured 40.94 ch. between K-9 and K-10, measured 40.16 ch between K-9 1887 and K-8, measured 40.75 ch. between K-9 and J-9. N31 3/4W 88.5 lks 18" Elm APPROVED 1964 Witnesses, O.M. Elliot, PS # 2097, Book 46, P. 2; Stone. County Remonumentation S72W 68.2' 6" Elm Peer Review Group 2300T1998 NCC Continued on Back. В. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K - 9 Section Corner, Sections 23,24,25 & 26, T8N-R3E, New Haven Township Found bent ½ " re-rod with an unreadable cap, and 2 accessories from 1986 (E leg sign to SSE at 20.20', and CMP to SW at 24.90' [was unable to measure to CMP, under water]). Measured South 2637.01' (39.95 ch.) to K-10 (1822 GLO 40.00 ch., 1887 C.S. rec. 40.94 ch. [39.94 ch. corrected]), measured East 2605.97' (39.48 ch.) to L-9 (1822 GLO 39.88 ch.). The position of the bent ½ " re-rod & unreadable cap is accepted as the best available evidence of the position of the original government corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: K - 10 Section Corner, Sections 23,24,25 & 26, T8N-R3E, New Haven Township Set a standard 20" Harrison monument at the position approved by the Shiawassee County peer review group. OF MICHIN S02E 20.04 E-leg Arrow Sign South 36.63' Found Nail & Tag # 24622 W Fc 14" Poplar

Set 1/2 " Rod & Cap # 39096 in ditch bank OFERSIO Stop Sign Post IN NE -(MONUMENT BOX INSTALLED PAVEMENT 23 OCT 1998

accert

Date

MIN H

RAUSER

Signed by Surveyor's Michigan License No. 39096

33.49'

45.44'

177.73' Set Nail & Tag # 39096 NW Fc P/P

158.95' Set Nail & Tag # 39096 N Fc 20" Willow

\$45W

S60E

N45E

**N40W** 

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND 9 . IRVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1976** REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

## A. Continued:

1973 Witnesses, J. F. Quine, PS # 10704, Book 17, P. 35; Drove 6" iron railroad spike flush with pavement aligned over and double distance from 1/8 Post and 1/4 Post to East.

W leg of "Dead End" sign E leg of "Dead End" sign South 20.31 South 20.1 NW 41.3' Telephone cable marker Center of W end of 12" CMP road culvert NW 36.5'

NE 37.3 Center of E end of same culvert South 4.4 Center of sealcoat pavement

Survey, L. 1, P. 380, by John F. Quine, PS # 10704; Found iron stakes set by E. S. Brewer, Jr. 33' & 300' N. of 1/8 post in 1973 SW1/4 of Sec. 24. Establish 1/8 post from these, then extend line and double distance from 1/4 post to 1/8 post westerly to establish section corner. Measured 2605.5' between K-9 and L-9.

NW 41.3' Aluminum telephone cable marker NW 36.5' Center W end 12" CMP road culvert ΝE 37.3 Center E end of same culvert South 20.3 W leg of "Dead End" sign South 4.4 Centerline of road

LCRC, L. 1, P. 534, by John F. Quine, PS # 10704; Reestablished at point indicated by extending line and doubling distance 1975 over 1/8 post & 1/4 post to East. Drove 6" iron railroad spike flush with sealcoat pavement. Measured 2605.50' between corners K-9 and L-9.

> South 20.3' W leg of "Dead End" sign South 20.1 E leg of "Dead End" sign NW Telephone cable marker 41.3 NW 36.5 Center of W end of 12" CMP road culvert NE 37.3 Center of E end of same culvert South 4.4' Center of sealcoat pavement East 1,302.75' 1/8 Post 2605.50' 1/4 Post East

1986 Survey, L. 4, P. 483, by Mark L. VanRaemdonck, PS # 24622; Found R.R. Spike.

N50W 37.80' SE Fc road sign post N55W 40.97 Top center Tel. cabinet S20W 24.90' Top center 12" CMP S02E 20.20' E leg arrow sign

1995 Survey, L. 7, Pgs. 361-362, by Mark L. VanRaemdonck, PS # 24622; Found R.R. Spike; measured 2659.52' between corners K-9 and K-8, measured 2689.75' between corners K-9 and J-9.

N50W 37.80 SE Fc road sign post N55W 40.97 Top center Tel. cabinet **\$20W** 24.90 Top center 12" CMP S02E 20.201 E leg arrow sign

SURVEY & REMONUMENTATION

NOV 0 3 1998

SECTION





3007716 Page: 2 of 2 10/27/1998 03:22P

Lb-1 Pg-269