Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			RECORDED 95 SEP -5 PM 1:48					
Shiawassee COMMISSIE Rated In:	Corner Code #							
1. Public Land Survey	M-12	SHIAMASSEE COUNTY, MICH. Register of Deeds Stamp & File Number						
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R								
4. Lot No, Recorded Plat 5. Private Claims			вс	D E F	G H	1 J)	K L	
			.6	5 4	3	2		
I, Norman C. Caldwell , in a field survey do hereby certify that under requirements of P.A. 74, Michigan P.A.	on May 25, 19 95	3 -	7	8 - 9-	-10	11	12	
In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5		5 - 6 - 7 -		17 16	15-	14	13	
above were in conformance with the rules of the Michigan Board Court of Law; established, re-established, monumented, re-expressed below:	of Land Surveyors or by a Decree of a -monumented, recovered, found as	8	.19	20 - 21 -	- 22	23	24	
NOTE: Not more than 4 corners, all in the same town on this certificate.	n and range, may be recorded	10	30	29 28	27	26-	25	
Description of original monument and accessories a	ind/or subsequent restoration:	12	31	32 33	-34	35	36	
M-12 Post placed by J. Wampler, 1822 N64°E 24.5 lks. (16.17') 11" Lynn S59°W 905 lks. (6.27') 8" ash	·	A John And		\\		<u> </u>	<u> </u>	
Survey by L. Mason May 20-22, 1878 Co. Surveyors Records p.176-177 N68°-35'E 58.25 lks. (38.44') 24" elm L.C.R.C. by M.L. Vanraemdonk L.S. 2462 recorded Aug. 23, 1993 L. 2 P 859 & surv. Re-established location of the E. 1/4 cor. 1878, on file in drain office. Survey sh. T8N,R4E. This fits the E-W 1/4 line fenc. Well. Proportional method would place co: N3°-28'-53"W 108.90' 1/2" rerod @ W/ 1/2 West 24.44' set N&T in N. face R.R. tie N30°W 35.53' top cen. N. end 12" conc. co	2 July 22, 1993 rey in L 6 P 550-551 rer Sec. 36, T8N-R3E, based or ows a 1.65 chain jog at W. 1/4 e location. Other distances in the property of the property of the post	survey)	Province 5/95 by Lyma	M. C. m Mason	dated h			
N75°W 20.00' " " S. " " " " S0°-28'-53"E 2428.40' East 2.3' centerling B. Description of corner evidence found and/or method and second 1/2" bar per L 2 ¥ 859 which apparent conflicting evidence.	ne pav't, REI rerod & cap in M	g corner:			. There	: 1s n	٥	
C. Description of monument for corner and accessories 4-12 Standard East 1/4 Corner, Section 36, TBN-		the position	n of the	corner:				
Fnd record 1/2" Bar w/24622 cap flush with West. Replaced w/Earrison marker and Mon. re-establishment of the position of the or S85°W 24.43' 12018 tag in S. side R.R. N20°W 67.77' 12018 tag in E. side 2" ma North 108.90' 1/2" bar w/12018 cap (W 1/S88°W 40.02' 12018 tag in N side RR tie	n pav't, 2' +/- W. of painted box, and is accepted as a cariginal corner, tie fence post aple '4 Sec. 31) e fence post	centerlin reful and	faith	Eul	Mich	•		
Surveyor's Michigan License No. 120	. 0	APPROVED BY M	X	PTED FOR W	1018		SE COLUMN TO SERVICE S	

LIBER IR PG 110