1998 REMONUMENTATION PROGRAM

SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

NOV 0 3 1998

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

1 01 00111										
Shiawa: (County)		Located In: Hazelton Twp	Corner Code #	Kaye Grubba - Shi	Massee Co	RE		Pag 10/	07712 je: 1 c 27/1998 l Pg-2	03:2
1. Public Land Survey		T <u>8 N</u> R <u>4 E</u> T R T R	<u>K-10</u>	Regist	er of Deeds Stamp & File Number					
in Sec 3. Miscel Prope	laneous S rty in Sec. S	T R T R		NOVED Pronumentation Proview Group	, , A B	СР	E F G	Э H	ΙJΚ	L
4. Lot No 5. Private	o, Recorded Pla e Claims	ıt		eview Group	2 6 3	5	4	3	2	1
l,	ohn H. Rauser, P.S.	,in a field survey on_	<u>Februar</u>	<u>/ 9, 19 98 , </u>	4 7	8	9	10	17-	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points in lines 1 and 2 above were in conformance with regulations and rules therefore as requirement manual of survey instructions of the United States Department of the Interior, Burea Management or by a decree of a Court of Law and/or that the corner points mentioned in lines above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Court of Law; established, re-established, monumented, re-monumented, recovered,				ne comer points mentioned erefore as required in the Interior, Bureau of Land	6 18	17	16	15	14	13
				vevors or by a Decree of a	8 119	- 20	21	22	23	24
expressed below:				10 30	29	28	27	26 6	25	
	lot more than 2 corne n this certificate.	rs, all in the same t	own and range, n	nay be recorded	11 31	32	33	34	35	36
<u>K-10 1</u> 1:	876 Survey by Lym ch. between K- 912 Shiawassee Co (388') East of C 972 CPCo Un-reco on line fences,	25 & 26, T8N-R4E, Haced by Joseph Wamp an Mason, C.S. refer 10 and L-10. county Drain Records, corner. rded survey by E. J. I no witnesses. Meas	azelton Township oler D.S.: renced post, No de minutes of survey McCombs, P.S. # ured 2647.99' (40.	For subsequent restor Beech 8 East, 10 links Beech 10 N70W, 22 links escription of monument grant, Cronk Drain, reference 10696, F.B. 1270, DWG, 12 ch.) between K-10 ar	s given, No a s the cent	erline of	f the drai	n to be	5.88 ch	١.
<u>K-10 1</u>	2623.74' (39.78	5 ch.) between K-10 a vidence found an 5 & 26, T8N-R4E, Ha	and L-10. d/or method ap azelton Township	plied in restoring or						

Occupied line between two farm fields to the West of the recovered corner.

Measured North 2648.01' (40.12 ch.) to K-9 (1822 GLO 40.00 ch., 1972 rec. 2647.99'), measured South 2648.00' (40.12 ch.) to K-11 (1822 GLO 40.00 ch., 1972 rec. 2647.99'), measured East 2623.71' (39.75 ch.) to L-10 (Intersection of 1/4 Lines)(1876 C.S. rec. 39.61 ch., 1976 rec. 2623.74'). We accept the position of the bent ½ " re-rod as the best available evidence of the position of the original government corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/4 Corner, Sections 25 & 26, T8N-R4E, Hazelton Township

Set a standard 20" Harrison monument at the position approved by the Shiawassee County peer review group

N40W 25.57 Set rod & cap # 32332 on ditch bank N40E 29.50" Set rod & cap # 32332 on ditch bank S40E 33.35 Set rod & cap # 32332 on ditch bank S35W 31.87 Set rod & cap # 32332 on ditch bank

aur Signed by Surveyor's Michigan License No. 39096



TATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING MARCH, 1983