## **SURVEY &** REMONUMENTATION

FEB 08 2001




SECTION

2000 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATERECEIVED FOR RECORD

|   |                         | Requirement of Act 74,<br>Mich. P.A. 1970 | LIBE       | R NO.                                    | 411   | ı <b>A</b> ∫i | rbe                     | 12     |              |    |
|---|-------------------------|---|------------|--|-------|---------------|-------------------------|--------|--------------|----|
| For corners in: ARBELATWP.  |                         | 10121 172 1010                            |            | ODDEC 19 PM 1:36  OUTH TO STATE OF DEEDS |       |               |                         |        |              |    |
|   |                         | Corner Code #                             | 0          |  |       |               |                         |        |              |    |
| 1. Public Land Survey   | T_10N R_7E_ T R T R T R | <u>L-5</u>                                | 6          | TUS<br>REG                               | WTTER | COU<br>OF D   | )<br>PLL<br>NTY<br>EERS | $\cap$ |              |    |
| 2. Property Controlling   | S T                     | R   |            |  |       |               |                         |        |              |    |
| in Section  | S T                     | R   |            |  |       |               |                         |        |              |    |
| 3. Miscellaneous S T R  |                         |   |            | Register of Deeds Stamp & File<br>Number |       |               |                         |        |              |    |
| Property in Sec.  | S T                     | R   | t- <u></u> |  |       | ······        |                         |        |              |    |
| 4. Lot No   | , Recorded Plat         |   |            |  |       |               |                         |        |              |    |
| 5. Private Claims   |                         |   | 1          | а в                                      | c D   | E I           | F G                     | H I    | J            | K  |
|   |                         | •   | 2          | 6  | j     | !             | 9                       | 3      | 2_           | +- |
|   |                         |   | 3          | -  |       | +             | +-                      | +      | +            |    |
| I, <u>Kari M. Lohela</u> , in a field survey on <u>August 29</u> , 20 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current were in conformance with regulations |                         |   |            | ,<br>                                    | 8-    | 9<br>         | -                       | 1.0    | _ i1_        |    |
|   |                         |   |            |  | 17    | -1            | 6                       | 15     | — 1 <b>4</b> |    |
| United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of the Michigan Board of Land Surveyors or         |                         |   |            |  |       |               |                         | +-     | -            | -  |
| by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:  |                         |   | ed,        | 1/9                                      | 20    | - 2           | 1-                      | 22     | -2 3         | 2  |
| a section manages was request   |                         |   | 9          |  | 1 1-  |               | <del></del>             | +      |              | +  |

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

1822 G.L.O. NOTES, JOSEPH FLETCHER, D.S., SET  $\frac{1}{4}$  CORNER POST, BIRCH 16 S 47 E 16, ASH 9 N 19 E 27

AUG 22, 1888, JOHN TESKEY, SURVEYOR, STAKE ESTABLISHED AT CORNER, BEECH 12 S 24 W 12

APRIL 19, 1971, SURVEY L.1 P.2, DAVID ROWE, PS 11192, NO MENTION OF OBJECT FOUND OR SET, N 5 E 52.8' P.P., SOUTH 34 .8' FENCE POST

AUG 15, 1971, LCRC P.13, ARBELA TWP., DAVID ROWE, PS 11192, FOUND RE-ROD, NORTH 33.0' PROPERTY CORNER, SOUTH 34.8' FENCE CORNER POST, N 05 E 52.8' P.P., SOUTH 2.7' CENTERLINE ASPH.

APRIL 24, 1972, LCRC P.14, ARBELA TWP., GERALD MCKELVEY, PS 19001, FOUND 1/2" RF-ROD AT CENTERLINE OF MILLINGTON ROAD AT EXTENSION OF OCCUPATON LINE, NE 53.50' SURVEYOR'S DISK IN UTILITY POLE, SOUTH 34.92' SURVEYOR'S DISK IN FENCE POST, SE 49.35' SURVEYOR'S DISK IN MAIL BOX POST

JULY 27, 1972, SURVEY L.2 P.37, DAVID ROWE, PS 11192, OBJECT AND ACCESSORIES SAME AS IN LCRC P.13, ARBELA TWP.

SEPT. 23, 1972, SURVEY L.2 P.105, DAVID ROWE, 11192, OBJECT AND ACCESSORIES SAME AS IN SURVEY L.1. P.2 NOV. 19, 1974, SURVEY L.453 P.496, DAVID ROWE, PS 11192, NO MENTION OF OBJECT OR ACCESSORIES

APRIL 16, 1975, SURVEY L.452 P.643, JAMES BECK, PS 21559, OBJECT AND ACCESSORIES SAME AS LCRC P.13, ARBELA TWP.

APRIL 9, 1984, SURVEY L.542 P.391, WILLIAM WINIARSKI, PS 23857, OBJECT AND ACCESSORIES SAME AS IN LCRC P.13, ARBELA TWP.

NOV. 19, 1992, SURVEY L.636 P.884, JONATHAN FIELD, PS 37276, FOUND  $\frac{1}{2}$ " ROD, NORTH 33.0' PROPERTY CORNER, N 05 E 52.80' P.P., S 60 E 51.16' TOP CENTER E. END 15" CMP, N 45 E 31.36' TOP CENTER W. END 15" CMP, SOUTH 1.7' CENTERLINE ASPH. ROAD, S 65 E 45.70' CENTER MAILBOX POST

22, 1999, SURVEY L.789 P. 885-886, JONATHAN FIELD, PS 37276, FOUND ½" ROD IN MON. BOX, SOUTH 49.88' 1/2" ROD, S 45 E 51.16' NOTCH IN W. END 24" CMP, N 20 E 53.25' NAIL & TAG #40162 IN W FACE P.P., N 40 E 31.42' NOTCH IN W. END 18"CMP

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" REBAR IN MONUMENT BOX ON EXTENSION OF OCCUPIED LINES TO NORTH AND SOUTH. RECOVERED 5 ACCESSORIES WHICH INDICATE THAT 1/2" REBAR IS IN SAME POSITION AS SURVEYS AND LCRC'S CITED ABOVE

ACCEPTED FOUND 1/2" REBAR AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER POSITION.

Description of monument for corner and accessories established to perpetuate locating the position of C. Descri the corner:

PLACED STANDARD BRASS CAP STAMPED L-5, T10N-R7E, OVER ½" BAR. ENCASED CAP AND BAR IN CONCRETE IN EXISTING MONUMENT BOX.

NORTH, 32.91' FOUND 1/2" REBAR

N 12° E, 53.26' SET REMON. TAG & NAIL ABOVE FOUND #4062 TAG IN SW FACE OF UTILITY POLE S 10° E, 31.88' FOUND NOTCH IN CROWN AT W. END OF 15" CMP CULVERT S 45° W, 51.18' FOUND NOTCH IN CROWN AT E. END OF 15" CMP CULVERT

